



98th and Bluewater

Bluewater Road
Albuquerque, NM 87121-2576
98th and I-40 Land, LLC.

Completed By: Cassandra Durkin

Date: August 2, 2020

Weather Event Inspection

Permit #: NMR100339

Report Creation Date: August 2, 2020 at 3:25:56 PM MDT



24h Precipitation: **0.04"**



48h Forecast: **20%**

Task Items

Responses

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

a. Site Inspection

1. Are there any erosion control structures damaged from the rain event?

Yes

Notes:

Silt fence is damaged on the North side of b Bluewater.

2. Are there signs of new ruts or gullies from the rain event?

Yes

Notes:

3. Are there signs of significant amounts of mud in the street or outfalls from the rainfall event?

Yes

Notes:

South side of Bluewater shows signs of traffic rills

4. Are there any conditions that need immediate attention?

Yes

Notes:

Silt fence needs to be installed on the south side of Bluewater

Part 2: Inspection report summary.

b. Inspection Report Summary

1. Qualifications of Inspector:

Training and work experience – see inspector qualification page in the SWPPP.

2. Measures/Areas Inspected:

Entire site

3. Observed Conditions:

Site is clean with minor housekeeping needed at inlets

4. Changes Necessary to the SWPPP:

No

5. Were there any discharges?

No

Notes:

6. What did the water look like at the time of the discharge?

Notes:

7. Was Inspection Conducted Within 24 Hours of Last Rainfall Over 1/4"?

Yes

Notes:

8. How much did it rain?

Reference precipitation values included with this form.

Notes:

0.47"

Certification

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X Cassandra Durkin

Signature Date

August 2, 2020

Title

X Environmental Compliance Manager

Notes

August 2, 2020

Location Description:

Images: 

Action Items

Title	Inspector	Date	Priority	Location	Description	Closed	Closer	Closed Notes	Imgs
Clean Inlet Protection	Cassandra Durkin	July 27, 2020	Immediate	Lat:35.08022321 Long:-106.74071413	Inlet protection is clogged				

