



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	L & C Transport Office				
Location:	108 94th Street NW				
Site Contact Name & Agency	F&J Home builders	ESC File No.	K09E043		
	Lorenaj89@gmail.com	NPDES Id. No.	NMR10032W		
Inspection Date:	08/12/20	Start/End Time:	0910/0920hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	78*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	No issues observed with this inspection.		
	Please forward the latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 6/18/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/12/20