

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	K09E0				Southern Tire Mart			
NPDES Id. No. NMR10044B/		I I			8201 Daytona Rd NW			
	5/2023	Owner			Contractor			
Operator		Southern Tire Mart, LLC		TL Wallace				
Contact name & title		Rick Yarborough						
e-mail			ough@stmtires.co	<u>m</u>				
Contact Phone #		505-917-6442						
COA Inspector		Chancellor English			Start/End Time:		PM	
Construction Phase:					nearly complet			
	nspection:	Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up						
Weath	er at time of i	nspection?	Clea	r	Temper	ature: ~	80	
Estimated date of last storm 0.25" or greater 5/22/2023								
Item								
Number	Deficiency/ Corrective Action							
	Your NPDES Permit coverage was not posted for safe, public viewing. You must post a sign or other							
	notice of your permit coverage at a safe, publicly accessible location in close proximity to the							
	construction site. The notice must be located so it is visible from the public road that is nearest to the							
	·							
	active part of the construction site, and it must use a font large enough to be readily viewed from a							
	public right-of- way per CGP 1.5.							
	The SWPPP is missing all owner/operator signatures. As per CGP 7.2.10, the SWPPP must be signed and							
	dated in accordance with CGP Appendix G, Part G.11							
	Your contractor's NOI is not included in the SWPPP. As per CGP 1.1.1, all operators must obtain permit							
	coverage.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports		Latest rep	oort Date:			
Notes:	otes: Contractor's NOI is still missing from SWPPP. Permit coverage posting had incorrect							
NPDES IDs. The contractor held the SWPPP in his vehicle								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English