

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No. K09E					Southern Tire Mart			
NPDES Id. No. NMR10044B/		l l			8201 Daytona Rd NW			
6/5/2023		Owner		Contractor				
Operator 8 +i+l-		Southern Tire Mart, LLC Rick Yarborough			TL Wallace			
Contact name & title e-mail		rick.yarborough@stmtires.com						
Contact Phone #		505-917-6442						
					Chaut/Find Time	2.00	DN4	
COA Inspector Construction Phase:		Chancellor English			Start/End Time: 2:00 PM			
Type of Inspection:		Regular Storm Event Post Storm			nearly complete Event >0.25" 311/Complaint Follow Up			
Weather at time of i			Clea			erature: ~	80	
Estimated date of last s				<u> </u>	Гепре	5/22/2023	80	
	Santa Co. 1885 Statistical Co.							
Item Number		Deficiency/ Corrective Action						
	Your NPDES Permit coverage was not posted for safe, public viewing. You must post a sign or other							
	notice of your permit coverage at a safe, publicly accessible location in close proximity to the							
	construction site. The notice must be located so it is visible from the public road that is nearest to the							
	·							
	active part of the construction site, and it must use a font large enough to be readily viewed from a							
	public right-of- way per CGP 1.5.							
	The SWPPP is missing all owner/operator signatures. As per CGP 7.2.10, the SWPPP must be signed and							
	dated in accordance with CGP Appendix G, Part G.11							
	Your contractor's NOI is not included in the SWPPP. As per CGP 1.1.1, all operators must obtain permit							
	coverage.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports		Latest rep	oort Date:			
Notes: Contractor's NOI is still missing from SWPPP. Permit coverage posting had incorrect								
NPDES IDs. The contractor held the SWPPP in his vehicle								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov