

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. K09E		050   Project Name:		Bluesky Distributing Tract 9B			
NPDES Id. No. NMRTC		USID Location:		Bluewater Rd and Daytona Rd			
6/5	72023	Owner			Contractor		
Operator		Aspen and Autumn LLC					
Contact name & title		Robert Poole					
e-mail		blueskyrobert@yahoo.com					
Contact Phone #		263-4047					
COA Inspector		Chancellor English			Start/End Time:	2pr	n
Construction Phase:			lo. = .1		ructure	lande at the	Te. 0 (1)
	spection:	Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~ 80							
Estimated date of last storm 0.25" or greater 2/15/2023							
Item Number	Deficiency/ Corrective Action						
1	Your NPDES permit coverage was not posted for public viewing. You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site. The notice must be located so it is visible from the public road that is nearest to the active part of the construction site, and it must use a font large enough to be readily viewed from a public right-of- way per CGP 1.5.						
2	Your SWPPP was not available on-site at time of inspection, nor was a sign posted giving the location of your SWPPP. Your SWPPP must be kept up-to-date per CGP 7.1 and available on-site per CGP 7.3. If an on-site location is unavailable to keep your SWPPP when no personnel are present, notice of the plan's location must be posted near the main entrance of your construction site CGP 7.3.						
2.1	Discharge off site?  Self Inspect	(Y/N) ion Reports	no Yes	Latest rep	port Date:	6/1/20	23
Notes:		Teve					
Land has b	een disturbe	d on proper	ty and construct	ion has begu	n on a new ad	ccess road.	
		, , ,	•				

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Chancellor English (505) 924-3325

cenglish@cabq.gov

