



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	K09E050	Project Name:	Bluesky Distributing Tract 9B		
NPDES Id. No.	NMR10051D	Location:	Bluewater Rd and Daytona Rd		
8/30/2023	Owner	Contractor			
Operator	Aspen and Autumn LLC				
Contact name & title	Robert Poole				
e-mail	<a href="mailto:blueskyrobert@yahoo.com">blueskyrobert@yahoo.com</a>				
Contact Phone #	263-4047				
COA Inspector	Chancellor English	Start/End Time:	9:30am		
Construction Phase:	infrastructure				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input checked="" type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	85	
Estimated date of last storm 0.25" or greater	8/8/2023				

Item Number	Deficiency/ Corrective Action			
1	SWPPP			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	Yes	Latest report Date:	8/10/2023

Notes:	SWPPP located in building on north lot. In process of stabilizing
Previous inspection violations were all mitigated: NOI is both posted and located in SWPPP located at active construction site north of lot (Titan (Spec) 150K) but still needs to certify SWPPP.	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Chancellor English (505) 924-3325  
[cenglish@cabq.gov](mailto:cenglish@cabq.gov)