

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:	Vitality Works						
Location:	8500 Bluewater NW						
Site Contact Name &	Daniel Ree	eves ESC File No. K10E009					
Agency	Insight Cor	nstruction		NPDES Id. No.		nmr100182	
Inspection Date:	02/15/19	Start/End Time:	130	00/1345hrs			
CoA Stormwater Inspec	ctor:	Timothy Sims, Stormwater Inspector					
Present Phase of	interior work on building						
Construction:							
Type of Inspection:	Regular	Storm Event		Post Storm I	vent >0.25"	311/Complaint	x Follow Up
Weather at time of inspection?			Tempe	rature: ~	58		
	Clear						
Has there been a storm event since site was Permitted?							

Cidilly dillount. (1.e., \1/4 to \2)/4 j. yes, \2)/4	Clarify amount: (i.e <1/4" to >3/4"):	yes, >3/4"
--	--	------------

inspection

		inspe	CUOII
CGP Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
000000	Doct o Notice	Required	
1.5	Provide and maintain Natural buffer when		
2.2.1	Waters of the US <50ft.		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter	Х	reconstruct silt fence on south side of site
2.2.3	Sediment control along any perimeter		reconstruct silt fence on east side of site
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track out		

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)			
4	Self Inspection Reports	requested	Latest report Date:	
Notes: (City	Inchector Lical Items in compliance	e can he left hlank	,	

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	please forward the latest self inspection report

City of Albuquerque		
Contact information: Timothy Sims, 505-803-6155 or		02/15/19
	tsims@cabq.gov	

Construction General Permit (CGP)