

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name and Location		Vitality Works 8500 Bluewater NW							
Site Contact Name & Agency		Daniel Reaves Insight Construction			ESC File No. NPDES ID No.		K10E009 NMR1001EF- Vitality Works		
Date of Inspection		11/09/18			Start/End Time 12:20pm - 12:30pm				
COA Inspector Name		Cassandra Durkin, Stormwater Quality							
Describe Present Phase of Construction		Slab Poured							
Type of Inspection:									
☐ Regular ☐ During storm event ☐ Post-storm event (> 0.25 inch) ☐ 311 / Complaint Response ☐ Follow-Up									
Weather Information									
Weather at time of this inspection? ☐ Cloudy ☐ Rain ☐ Sleet ☐ Fog ☐ Snowing ☐ Windy ☐ Windy							perature: ~ 50 F°		
	ere been a storm event sin nt: $\square < \frac{1}{4}$ " $\square \frac{1}{4}$ " to $\frac{3}{4}$			Yes □No]Snow "					
			Inspecti	on					
Corrective									
CGP	BMP / Activity	Maintenance Required? (1)	Action Required? (2)	Location and	l Notes				
1.5	Post a Notice								
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.4	Minimize sediment track-out								
2.2.5	Manage stockpiles								

2.2.6	Minimize Dust						
2.2.10	Protect Storm Drain Inlets						
2.2.10	Protect Storm Drain Inlets						
2.2.11	Minimize erosion of conveyance channels						
2.2.12	Sediment Basins						
2.2.14	Stabilize exposed portions of the site.						
2.2.14	Stabilize exposed portions of the site.						
2.2.14	Stabilize exposed portions of the site.						
2.2.14	Stabilize exposed portions of the site.						
2.3.1	Equipment and Vehicle Fueling						
2.3.2	Equipment and Vehicle Washing						
2.3.3	Building Material Storage						
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage						
2.3.3	Construction and Domestic Wastes						
2.3.3	Construction and Domestic Wastes						
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.						
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.						
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.						
2.4	Dewatering						
2.1	Discharge off site?		□Yes X No				
4	Self-Inspection Reports			Latest Report Date:			
Notes:	tes: (City Inspector Use) Items in compliance can be left blank.						

(1) Maintenance is to be complete by the end of the next business day.

(2) Corrective Actions are to be complete within 7 days.

Notes:	Site was locked. There is a large area of disturbance ou	utside o	f the	projec	t area.	Offsite drainage fr	om
	disturbed areas is not permitted.		_(\	1			

City of Albuquerque Stormwater Inspector Signature and Date.

11/05/18 Date

Signature

Contact Info: Cassandra Durkin, CESSWI 505-924-3983, cdurkin@cabq.gov