

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	K10E0				541 Airport			
NPDES Id. No. NMR10					541 Airport Dr NW			
7/2/2024		Owner			Contractor			
Operator		Brunacini Builder Opportunity Land LLC			GA Brunacini Construction Co. Inc.			
Contact name & title		Angelo Brunacini			Angelo Brunacini			
e-mail Contact Phone #		gbrunacini@brunacini.com 505-833-2928			gbrunacini@brunacini.com 505-833-2928			
					1			
COA Inspector		Chancellor English			Start/End Time: 2pm			
Construction Phase: Type of Inspection:		verticals Regular Storm Event Post Storm Event > 0.25" 31						
		Regular	Storm Event			311/Complaint	Follow Up	
	er at time of i		Clea	ar	Temper	ature: ~	95	
Estimated date of last storm 0.25" or greater 6/30/2024								
Item	Deficiency/ Corrective Action							
Number	Deficiency/ Corrective Action							
1	None							
				<u>, </u>				
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	Yes	Latest rep	oort Date:	6/27/20)24	
Notes:								
Construction crew was in process of cleaning track-out at the time of inspection.								
Construction crew was in process of cleaning track-out at the time of inspection.								

City of Albuquerque Stormwater Inspector Signature and date: 7/5/2024

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English