

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:	Defined Fitness @ Unser Crossings						
Location:	Unser & Centals - SW corner						
Site Contact Name &	David Lopez- Guzman		ESC File No.		K10E045B		
Agency	d.lopez@guzmancs.com		NPDES Id. No.	NMR1001X7			
Inspection Date:	03/21/19	Start/End Time:	1030/1130hrs				
CoA Stormwater Inspector:		Timothy Sims, Stormwater Inspector					
Present Phase of			over ex., o	over ex., clear & grub			
Construction:							
Type of Inspection: x	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Weather at time of inspection?				Tempe	erature: ~	48*	
cloudy/windy					_		
Has there been a storm event since site was Permitted?							

Clarify amount: (i.e.. <1/4" to >3/4"):

Inspection					
CGP Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes		
1.5	Post a Notice	·			
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.				
2.2.3	Sediment control along any perimeter	х	northern silt fence requries maintenance		
2.2.3	Sediment control along any perimeter	Х	install track out pad/ sweep track out		
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.4	Minimize sediment track out				

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes	Х	litter on site - clean
2.3.3	Construction and domestic wastes		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	
	City of Albumanage Champanatay Incorporate Cignotius and data.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy Sims, 505-803-6155 or 03/21/19

tsims@cabq.gov

¹ Construction General Permit (CGP)