



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Defined Fitness @ Unser Crossings		
Location:	Unser & Central		
Site Contact Name & Agency	Joseph - Blanchard Properties <a href="mailto:rjones@jonescpa.com">rjones@jonescpa.com</a>	ESC File No.	K10E045B
		NPDES Id. No.	NMR1001X7
Inspection Date:	06/07/19	Start/End Time:	1220/1300hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	foundation and plumbing		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input checked="" type="checkbox"/> 311/Complaint <input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	63*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
1	Please provide the latest self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes:	Spoke with Joseph Superintendent. He called E2RC for reports.

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 06/07/19