

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Defined Fitness @ Unser Crossings					
Location:		Unser & Central					
Site Contact Name & Agency	Joseph - Blanchard Properties			ESC File No.	K10E045B		
	rjones@jonescpa.com			NPDES Id. No.	NMR1001X7		
Inspection Date:	07/10/19	Start/End Time:	0830/0900hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		foundation and plumbing					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	69*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
1	Please re-establish silt fence in the southwest corner of the site		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 7/3/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/10/19