



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Defined Fitness @ Unser Crossings				
Location:	Unser & Central				
Site Contact Name & Agency	Joseph - Blanchard Properties	ESC File No.	K10E045B		
	rjones@jonescpa.com	NPDES Id. No.	NMR1001X7		
Inspection Date:	07/18/19	Start/End Time:	0730/0745hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	73*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	previous issues resolved. No new issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 7/3/2019

Notes:	Thanks for mitigating silt fence issues on the southwest corner.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/18/19