City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Defined Fitness @ Unser Crossings		
Location:	Unser & Central		
Site Contact Name & Agency	Joseph - Blanchard Properties	ESC File No.	K10E045B
	rjones@jonescpa.com	NPDES Id. No.	NMR1001X7
Inspection Date:	12/30/19	Start/End Time:	1020/1025hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	STABILIZED		

Type of Inspection:										
	x	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up

Weather at time of inspection?	Clear	Temperature: ~	31*
Estimated date of last storm 0.25" or greater		11/27/2019	

Item Number	Deficiency/ Corrective Action			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

STABILIZED

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 12/30/19

Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.12.31 08:59:27 -07'00'