



## INSPECTION REPORT

### GENERAL INFORMATION

**DATE OF INSPECTION:** 9/16/2019

**COMPANY NAME:** Guzman Construction Solutions

**PROJECT NAME:** Defined Fitness at Unser Crossings

**LOCATION:** Westgate Heights, Unser Blvd., Albuquerque, New Mexico, 87121

**TRACKING NO:** NMR1001S5

**COMPLIANCE EVALUATION:** Marginal

**TYPE OF INSPECTION:** Rain Event

**START TIME:** 10:40 AM

**END TIME:** 11:00 AM

**INSPECTOR'S NAME:** Diana Baltazar

**INSPECTOR'S TITLE:** NPDES Inspector

**INSPECTOR'S QUALIFICATIONS:** StormwaterONE No: 6f93e116

**INSPECTOR'S CONTACT:** 505-379-2445

**PHASE OF CONSTRUCTION:** ☐ Clear and Grub ☐ Excavation ☒ Building (vertical)  
☐ Rough Grading ☐ Infrastructure ☐ Final Grading  
☐ Final Stabilization

**IF RAIN EVENT HOW WAS RAINFALL AMOUNT DETERMINED:** ☒ Rain Gauge ☐ Other Rain gauge

### WEATHER INFORMATION

**HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?** ☒ Yes ☐ No

**IF YES, PROVIDE:** Rain Event

#	STORM DATE	ESTIMATED STORM DURATION (HOURS)	APPROXIMATE PRECIPITATION (INCHES)
1	9/14/2019	.5	0.70

**WEATHER AT TIME OF THIS INSPECTION:** Clear

TEMPERATURE:

75

HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?

☐ Yes ☒ No

ARE ANY DISCHARGES OCCURRING NOW?

☐ Yes ☒ No

ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?

☐ Yes ☒ No

## POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	PHOTO
1	NPDES Permit Notification	None	None	Southeast Entrance	1	EA	<a href="#">Yes</a>
2	Silt Fence	Anchor	None	Perimeter	1750	EA	<a href="#">Yes</a>
3	Construction Entrance	None	None	Southeast Entrance	1	EA	<a href="#">Yes</a>
4	Contaminated Soil	Remove	None	West side of building	2	HR	<a href="#">Yes</a>

## GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
2	Are steep slope areas not actively being worked properly stabilized?	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
3	Are disturbed areas not actively being worked properly stabilized?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Curb and gutter installed, watering tank on site.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input checked="" type="radio"/> Yes <input type="radio"/> No	Existing curb and gutter have held sediment within construction site, but some silt fence needs to be re anchored. Contractor needs appropriately 800 LF of silt fence moved from existing position to or closer to the chainlink fence. Also drop inlets need protection.
5	Are discharge points and receiving waters free of any sediment deposits?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
6	Is trash/litter from work areas collected and placed in covered dumpsters?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input checked="" type="radio"/> Yes <input type="radio"/> No	Dumpsters on site, trash and debris is discarded appropriately. Some white powdered substance (assumption either paint or limestone) found on south side of building needs to be removed.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
10	Are offsite flows entering the construction site?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	None observed during inspection.
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
13	Are non-stormwater discharges properly controlled?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
15	Are changes to the SWPPP necessary at this time?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
16	Are dust control measures being properly implemented?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	

**CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

**INSPECTED BY:** Diana Baltazar **DATE:** September 16, 2019

**SIGNATURE AND AFFILIATION:**



**CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

**PRINT NAME AND TITLE:** , **DATE:**

**SIGNATURE:**