

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	K10E				7200 Bluewater			
NPDES Id. No. NMR10		003UT Location:			7200 Bluewater			
2/28	8/2022	Owner			Contractor			
Operator		M & B Investments Ltd. Co.			GA Brunacini Construction			
Contact name & title		Angelo Brunacini			Angelo Brunacini			
e-mail		abrunacini@brunacini.com			abrunacini@brunacini.com			
Contact Phone #		505-833-2928			505-833-2928			
COA Inspector		Doug Hughes			Start/End Time: 3pm			
Construction Phase:					hwork			
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	clea	r	Temper	ature: ~	60	
Estimated date of last storm 0.25" or greater 1/1/2022								
Item								
	Deficiency/ Corrective Action							
Number								
1	Permit coverage was not properly posted, dsign was laying on the ground but still ledgible.							
2	Minor washout next to the container needs disposed in the waste container.							
	·							
3								
5								
4								
5								
J								
2.1	Discharge off site?	(Y/N)	yes					
4	Self Inspect	tion Reports	Requested	Latest rei	port Date:			
•								
Notes:								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-803-6155)

jhughes@cabq.gov

3/2/2022

James D. Hughes