
EXHIBIT 'A' TO IMPROVEMENT LOCATION REPORT

LEGAL DESCRIPTION:

LOT NUMBERED THIRTY-FIVE (35) OF **DANIEL G. HERRERA'S SUBDIVISION** OF TRACTS 203, 204 AND THE WESTERLY 118.70 FEET OF TRACT 205, UNIT 6 TOWN OF ATRISCO GRANT, ALBUQUERQUE, NEW MEXICO, AS THE SAME IS SHOWN AND DESIGNATED ON THE PLAT THEREOF, FILED IN THE OFFICE OF THE COUNTY CLERK OF BERNALILLO COUNTY, NEW MEXICO ON JULY 24, 1947 IN VOLUME C1, FOLIO 175.

This is not a survey for use by a property owner for ANY purpose.



PAGE 2 OF 2

Anthony L. Harris, N.M.P.S.#11463 HARRIS SURVEYING, INC. 2412-D Monroe Street, NE • Albuquerque, New Mexico 87110 Telephone (505) 889-8056 • FAX (505) 889-8645

The property shown hereon is _____ within tr

_ Dated: _

IMPROVEMENT LOCATION REPORT

THIS IS TO CERTIFY:	N7/4	IMINEDWOITED	
TITLE COMPANYLENDER	N/A N/A	UNDERWRITER that on	JUNE 19, 201.
I made an inspection of the prem			JONE 19, 201.
ALBUQUERQUE		LILLO County, New Me	.,
	listances and/or curve a lat). <u>G. HERRERA'S SUBD</u>	lata are taken from the following pa IVISION	
3			
GENERAL NOTES:			
		rror for every <u>N/A</u>	_feet along the
perimeter of the legal description Easements shown hereon are list shown above.		nent Noprovided by the	Title Insurance Company
question. (Page 2 of 2)		a complete Legal Description and	
This Tract is subject to all Easen		veys. No monuments were set with Reservations of record which perta	
in question. This report is not to be relied upo	on for the establishment	of fences, buildings and/or other f	uture improvements.
I FURTHER CERTIFY as to the of 1: Evidence of rights-of-ways, old water, gas or oil pipelines on of NONE	d highways or abandon	ed roads, lanes, trails or driveways	s sewer drains,
2: Springs, streams, rivers, ponds NONE	s of lakes located on or	bordering on or through the prope	rty in question.
3: Evidence of cemeteries or fam NONE	ily burial grounds locat	ted on the property in question.	
4: Overhead Utility poles, anchor questions and serving other pr		ines overhanging or crossing the p	roperty in
5: Joint driveways or walkways, common: <u>NONE</u>	joint garages, party wa	lls or rights of support, steps or roo	ofs used in
* *	ccupancy appear to enc	cornices thereof, or signs affixed to roach upon or overhang adjoining property in question.	
7: Specific physical evidence of b SEE SKETCH (PAGE	•	des of the property in question.	
8. Is the property in question imp YES	proved?		
9: Indications of recent building <u>NONE</u>	construction, alteration	s or repairs:	
10: Approximate distances of str		m at least two (2) property lines.	

Anthony L. Harris (Surveyor) N.M.P.M. # 11463

The above information is based on boundary information taken from a previous survey and may not reflect that which may be disclosed by a boundary Survey.

Page 1 of 2

anhangh - 7/



INVOICE

HARRIS SURVEYING, INC.

2412-D Monroe Street, NE Albuquerque, New Mexico 87110 (505) 889-8056 * Fax 889-8645

Habitat for Humanity P.O. Box 8353 Albuquerque, NM 87198 Date:

06/19/15

Order No.: 15-0352

Prepare an Improvement Location Report for:

908 Townsend Avenue S.W.

PAYMENT DUE UPON RECEIPT

Amount:

\$75.00

Tax:

5.25

Total Due: \$80.25