

INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION: 3/16/2020 Twilight Homes **COMPANY NAME:** Sunset Villa **PROJECT NAME:** LOCATION: 500 Twilight Vista Lane, Albuquerque, New Mexico, 87105 NMR1001H2 **TRACKING NO: Unsatisfactory COMPLIANCE EVALUATION: TYPE OF INSPECTION:** 14Day 11:30 AM **START TIME: END TIME:** 11:45 AM **INSPECTOR'S NAME:** Kasey Anderson **INSPECTOR'S TITLE: Environmental Inspector** Storm Water Qualified Person **INSPECTOR'S QUALIFICATIONS:** 505-280-7766 **INSPECTOR'S CONTACT:** PHASE OF CONSTRUCTION: ☐ Clear and Grub ✓ Excavation ✓ Building (vertical) ✓ Rough Grading ✓ Infrastructure ✓ Final Grading Final Stabilization

WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?

Yes

O No

IF YES, PROVIDE: Light to moderate rain

#	STORM DATE	ESTIMATED STORM DURATION (HOURS)	APPROXIMATE PRECIPITATION (INCHES)
1	3/12/2020	3	0.10
1	3/13/2020	3	0.10

WEATHER AT TIME OF THIS INSPECTION: Clear

TEMPERATURE: 60

HAVE ANY DISCHARGES OCCURRED SINCE	
THE LAST INSPECTION?	
ARE ANY DISCHARGES OCCURRING NOW?	

ARE ANY	PORTIONS	OF	YOUR	SITE	UNSAF	E
TO INSPE	CT?					

Yes	No

Yes

No

O Yes	No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
	Inlet Protection	None	Initial Install	Add inlet protections to inlets on Twilight Vista and Garden Way	5	EA	Yes
1	Inlet Protection	None	Initial Install	Add inlet protections to inlets on Twilight Vista and Garden Way	5	EA	<u>Yes</u>
, '	Inlet Protection	None	Initial Install	Add inlet protections to inlets on Twilight Vista and Garden Way	5	EA	<u>Yes</u>
	Inlet Protection	None	Initial Install	Add inlet protections to inlets on Twilight Vista and Garden Way	5	EA	<u>Yes</u>
2	Wattles/Socks/Lo g Roll	Update	None	1739 Garden Way; remove or add wattle in front of dirt pile.	25	LF	
3	Silt Fence	None	Replace	Replace 20ft section of silt fence at 605 Garden Patch	20	LF	
4	Sanilets	Anchor	None	Anchor portable toilet on Whitten Tr	1	EA	

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
2	Are steep slope areas not actively being worked properly stabilized?	• Yes ONO ON/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	● Yes ○ No ○ N/A	Yes No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	Yes No N/A	● Yes ○ No	Add inlet protections to inlets on Twilight Vista and Garden Way.
5	Are discharge points and receiving waters free of any sediment deposits?	○Yes ● No ○ N/A	• Yes No	Add inlet protections to inlets on Twilight Vista and Garden Way. Also, having dirt as curb ramps increases the likelihood of sediment being washed down the drains, so avoid using these.
6	Is trash/litter from work areas collected and placed in covered dumpsters?	• Yes O No O N/A	Yes No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	Yes No N/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes O No O N/A	Yes No	
10	Are offsite flows entering the construction site?	Yes No N/A	Yes No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	● Yes ○ No ○ N/A	• Yes No	Anchor portable toilet on Whitten Tr.
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	Yes No N/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	○Yes ● No ○ N/A	● Yes ○ No	Storm drain inlets need protection, especially since there are a lot of dirt curb ramps into Twilight lots.
15	Are changes to the SWPPP necessary at this time?	Yes No N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
16	Are dust control measures being properly implemented?	• Yes ONo ON/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	◯ Yes ● No	

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY: Kasey Anderson DATE: March 16, 2020

Thy filly

SIGNATURE AND AFFILIATION:

CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	The state of the s	DATE:

SIGNATURE: