

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:	Sunset Villa						
Location:	Sunset Gardens and Sunset Rd						
Site Contact Name &	Phil Lindborg-450-4388		ESC File N	١o.	K12E003		
Agency	Sunset Villa LLC		NPDES Id. 1	No.	NM12AX70		
Inspection Date:	02/22/19	Start/End Time:	0830/0920h	nrs			
CoA Stormwater Inspec	ctor:		Timothy S	Timothy Sims, Stormwater Inspector			
Present Phase of		-					
Construction:							
Type of Inspection: x	Regular	Storm Event	Post Stor	m E	vent >0.25"	311/Complaint	Follow Up
Weather at time of inspection?					Tempe	rature: ~	48*
clear/ windy							
Has there been a storm event since site was Permitted?							

Inspection

CGP	BMP / Activity	Maintenance or Corrective Action	Location and Notes
Section		Required	
1.5	Post a Notice		
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track out		

2.2.5	Manage stock piles				
2.2.6	minimize dust				
2.2.10	Protect storm drain inlets				
2.2.10	Protect storm drain inlets				
2.2.11	Minimize erosion of conveyance channels				
2.2.12	Sediment Basins				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.3.1	Equipment and vehicle fueling				
2.3.2	Equipment and vehicle washing				
2.3.3	Building material storage				
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage				
2.3.3	Construction and domestic wastes				
2.3.3	Construction and domestic wastes				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.4	Dewatering				
2.1	Discharge off site? (Y/N)	No			
4	Self Inspection Reports	requested	Latest report Date:		
lotes: (City Inspector Use) Items in compliance can be left blank.					

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	Please provide the latest self-inspection report

City of Albuquerque		
Contact information:	Contact information: Timothy Sims, 505-803-6155 or	
	tsims@cabq.gov	

Construction General Permit (CGP)