

	General Perm	it SWPPP Inspection	n		
Site Name: Legacy Central and Broadway Hotel		Inspector:	Marcos Valadez		
	99999 Union Square St SE, Albuquerque, NM 87102				
Permit #:	NMR1001MC NMR1001MD K14E017	Inspection Frequency:	Bi-weekly -		
Date of Visit:	Jul 15, 2021, 12:23:56 PM	Last Rain Event Thursday, July 15, 2021, 0.28"	Last Precipitation 48h Forecast Thursday, July 15, 2021, 0.28" 38% Chance of Rain		
Review each q	rm Instructions uestion for this inspection carefully, then answeress the "Add Action Item" button above to add		cable). If any of the items below are out of		
General In	formation				
Inspector's Q Trained and w	ualifications ork experience - see inspector qualification page	e in section 2 of the SWPPP.			
Type of Insp	ection:	✓	Regular During storm event		
		✓	Post-storm event		
Weather In	formation				
	ent Information n on the last storm event, see the weather even	t information at the end of	this inspection.		
Weather at t	ime of this inspection?	✓	Clear Cloudy Rain		
			Sleet Snowing High Winds		
			Partly Cloudy		
Have any dis	charges occurred since the last inspection	n?	No		
If yes, what d	lid the water look like at the time of the d	ischarge?	*		
Are there any	y discharges at the time of this inspection	Yes	No		
If yes, what d	id the water look like at the time of the d	ischarge?			
ls a rain gaug	ge installed on site?	Yes	No		
If yes, where	is it located?		presentative weather site is used to asure precipitation		
Has the Rain	Event Page been filled out?				

No



Site Name: Legacy Central and Broadway Hotel 99999 Union Square St SE, Albuquerque, NM 87102 Permit #: NMR1001MC NMR1001MD K14E017 Inspection Frequency: Bi-weekly Last Rain Event Thursday, July 15, 2021, 0.28" Thursday, July 15, 2021, 0.28" 38% Chance of Rain

	Jan 10, 2021, 12, 2000 1 111	Thursday, July 15, 2021, 0.28" Thursday, July 15, 2021, 0.28" 38% Chance of Rain
Are there SD	S sheets on site?	Yes No
If yes, where	are they located?	In the construction office
If construction	cion ceases on the site for more tha on resumes.	n 14 days, the site must be stabilized until
Date Constru	iction Stopped	
Date Constru	iction Resumed	
Measures Tal	ken to Stabilize the Site:	
Construction	and the state of the season of the season of the state of the season of	ord dates when activities started and were completed.
Installed BMF		Completed
Started:		
Completed:		03/20/19
Site Clearing a	and Grading	Completed
Started:		
Completed:		05/01/19
Installing Utili	ties	Completed
Started:		
Completed:		06/25/21



General Permit SWPPP Inspection Legacy Central and Broadway Hotel Site Name: Inspector: Marcos Valadez 99999 Union Square St SE, Albuquerque, NM 87102 Permit #: NMR1001MC NMR1001MD K14E017 **Inspection Frequency:** Bi-weekly -Last Rain Event Last Precipitation 48h Forecast **Date of Visit:** Jul 15, 2021, 12:23:56 PM Thursday, July 15, 2021, 0.28" Thursday, July 15, 2021, 0.28" 38% Chance of Rain

Building Structure	Started
Started:	10/08/20
Completed:	
Paving and Walks	Completed
Started:	
Completed:	06/29/21
Final Grading/Stabilize Site	Completed
Started:	
Completed:	07/15/21
Other	
Started:	
Site-specific BMPs	
The corrective actions initiated and date completed are in the Corrective Action Log	
List of BMPs Installed:	Portable toilets, roll off
Are all of the above controls installed?	Yes No
Do any of the above controls need maintenance?	Yes No
If any of the controls have not been installed or require maintenance, please list the control and explain.	



Site Name: Legacy Central and Broadway Hotel 99999 Union Square St SE, Albuquerque, NM 87102 Permit #: NMR1001MC NMR1001MD K14E017 Inspection Frequency: Bi-weekly Last Rain Event Thursday, July 15, 2021, 0.28" Thursday, July 15, 2021, 0.28"

Thursday, July 15, 2021, 0.28" Thursday, July 15, 2021, 0.28" 38% Chance of Rain Are the BMPs shown on the map? No Were there any changes to the SWPPP? Yes Has the SWPPP been updated? No Were the changes to the SWPPP implemented within 7 days? Yes List any new BMPs needed: Not need any BMP's the site has been stabilized with paving and concrete Notes: The site looked good at the time of inspection Oversight Issues A list of corrective actions will be supplied with this inspection. 1. Are all slopes and disturbed areas not actively being worked properly stabilized? Implemented? Yes No Maintenance Required? Yes No 2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs? Implemented? No N/A Maintenance Required? N/A Yes 3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained? Implemented? No N/A

Yes

N/A

Maintenance Required?



General Permit SWPPP Inspection									
Site Name: Legacy Central and Broadway Hotel 99999 Union Square St SE, Albuquerque, NM 87102 Inspector: Marcos Valadez									
Permit #:	NMR1001MC NMR1001MD K14E017	Inspection Frequency:	Bi-weekly -						
Date of Visit:	Jul 15, 2021, 12:23:56 PM	Last Rain Event Thursday, July 15, 2021, 0.28"	Last Precipitation 48h Forec Thursday, July 15, 2021, 0.28" 38% Chance of						

4. Are discharge points and receiving waters free of any sediment deposits? Implemented? No N/A Maintenance Required? Yes N/A 5. Are storm drain inlets properly protected? Implemented? Yes No Maintenance Required? No Yes 6. Is the construction exit preventing sediment from being tracked into the street? Implemented? Yes No Maintenance Required? Yes No 7. Is trash/litter from work areas collected and placed in dumpsters? Implemented? No N/A Maintenance Required? Yes N/A 8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained? Implemented? Yes No Maintenance Required? Yes No 9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material? Implemented? Yes No Maintenance Required

Yes

No



General Permit SWPPP Inspection Legacy Central and Broadway Hotel Site Name: Inspector: Marcos Valadez 99999 Union Square St SE, Albuquerque, NM 87102 Permit #: NMR1001MC NMR1001MD K14E017 **Inspection Frequency:** Bi-weekly -Last Rain Event Last Precipitation 48h Forecast **Date of Visit:** Jul 15, 2021, 12:23:56 PM Thursday, July 15, 2021, 0.28" Thursday, July 15, 2021, 0.28" 38% Chance of Rain

Implemented? Maintenance Required? Yes N/A 11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled? Implemented? Yes No Maintenance Required? N/A Yes No 12. Has the Site map been updated to reflect current conditions? Implemented? No N/A Maintenance Required? Yes N/A 13. Is the NOI posted? Implemented? No N/A Maintenance Required? N/A 14. Were previous corrections made within 7 days of last inspection or before the next storm event? Implemented? No N/A Maintenance Required? No N/A Yes

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes No

Have there been any reportable quantities releases of hazardous materials?

Yes



	General Permit SWPPP Inspection									
Site Name: Legacy Central and Broadway Hotel 99999 Union Square St SE, Albuquerque, NM 87102 Inspector: Marcos Valade:										
Permit #:	NMR1001MC NMR1001MD K14E017	Inspection Frequency:	Bi-weekly -							
Date of Visit:	Jul 15, 2021, 12:23:56 PM	Last Rain Event Thursday, July 15, 2021, 0.28"	Last Precipitation Thursday, July 15, 2021, 0.28"	48h Forecast 38% Chance of Rain						

Additional Notes

This is regular and rain event inspection 0.28†As soon as you get the C.O from City of abs. We can file the NOT (notice of termination)

Certification & Signatures

Certification Statement:

"l certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.â€

Electronic Signature

X Marcos Valadez Date July 15, 2021 at 3:56:44 PM MDT

Title Inspector



	General Permit SWPPP Inspection									
Site Name: Legacy Central and Broadway Hotel 99999 Union Square St SE, Albuquerque, NM 87102 Inspector: Marcos Valadez										
Permit #:	NMR1001MC NMR1001MD K14E017	Inspection Frequency:	Bi-weekly -							
Date of Visit:	Jul 15, 2021, 12:23:56 PM	Last Rain Event Thursday, July 15, 2021, 0.28"	Last Precipitation Thursday, July 15, 2021, 0.28"	48h Forecast 38% Chance of Rain						

Photos









General Permit SWPPP Inspection									
Site Name:	<u>Legacy Central and Broadway Hotel</u> 99999 Union Square St SE, Albuquerque, NM 87102	Inspector: Marcos Valadez							
Permit #:	NMR1001MC NMR1001MD K14E017	Inspection Frequency:	Bi-weekly -						
Date of Visit:	Jul 15, 2021, 12:23:56 PM	Last Rain Event Thursday, July 15, 2021, 0.28"	Last Precipitation Thursday, July 15, 2021, 0.28"	48h Forecast 38% Chance of Rain					

Weather History



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



General Permit SWPPP Inspection									
Site Name: Legacy Central and Broadway Hotel 99999 Union Square St SE, Albuquerque, NM 87102 Inspector: Marcos Valadez									
Permit #:	NMR1001MC NMR1001MD K14E017	Inspection Frequency:	Bi-weekly	-					
Date of Visit:	Jul 15, 2021, 12:23:56 PM	Last Rain Event Thursday, July 15, 2021, 0.28"	Last Precipitation Thursday, July 15, 2021, 0,28"	48h Forecast 38% Chance of Rai					

Action Items

Title	Inspector	Date	Priority	Location	Description	Status	Closer	Notes	Imgs
Mulch sock	Marcos Valadez	April 23, 2021	7 Days	West side of the site	Install mulch sock around the dirt pile and along the temp fence. See photos	Closed June 29, 2021	Marcos Valadez	Completed	Photo 1 Photo 2
Dirt piles	Marcos Valadez	March 26, 2021	7 Days	West side	Place a mulch sock around the dirt piles or remove them.	Closed June 29, 2021	Marcos Valadez	Completed	Photo 1 Photo 2