

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:		Presbyterian Healthcare Services							
Location:		1100 Central Ave SE							
Site Contact Name &		Jeff Smith - jeff.smith@jaynescorp.com ESC File No. K15E005							
Agency		Jaynes Corp		NPDES Id. No.	Ownr: N	IMR1002G1/ OP: NMR1002FV			
Inspection Date:		01/24/20 Start/End Time: 1245/1305hrs							
CoA Storm	water Inspecto	r: Ti	mothy E. Sims						
Construction Phase:		interior							
Type of Inspection: x		Regular Storm Event		Post Storm Event >0.25" 311/Complaint Fo		Follow Up			
Weather at time of i		inspection? Clea		nr	Temperature: ~ 50*		50*		
Estimated	date of last s	torm 0.25" oi	r greater			11/27/2019			
Item									
			Deficienc	y/ Correctiv	e Action				
Number									
	no issues observed with this inspection								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspect	tion Reports		Latest rep	oort Date:	1/21/20	020		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155