



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	K15E005	Project Name:	Presbyterian Healthcare Services		
NPDES Id. No.	NMR1002G1;NMR1002FV	Location:	1100 Central Ave. SE		
5/18/2021	Owner	Contractor			
Operator	Presbyterian Healthcare Services	Jaynes Corporation			
Contact name & title	Jim Jepsson	Jeff Smith			
e-mail	jjepson@phs.org	jeff.smith@jaynescorp.com			
Contact Phone #	505-814-1769				
COA Inspector	Thomas Evans	Start/End Time:	3:25 PM/3:40 PM		
Construction Phase:	Building construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	rain	Temperature:	~	54	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	Sediment in the street. Sweep track-out and remove sediment from the gutters (CGP 2.2.4)				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	8/4/2020	

Notes:	Spoke with Jan Nakotte. Crew are sweeping trackout daily. Inlet protection looks great.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/20/2021