



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Springhill Suites	
Location:		1101 Central	
Site Contact Name & Agency	Jeff Harper	ESC File No.	K15E034B
	<a href="mailto:jeff.harper@jaynescorp.com">jeff.harper@jaynescorp.com</a>	NPDES Id. No.	NMR1001RP
Inspection Date:	02/11/20	Start/End Time:	1230/1300hrs
CoA Stormwater Inspector:		Timothy E. Sims	
Construction Phase:	vertical with site work		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input checked="" type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Ptly Cloudy	Temperature: ~	34*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 2/11/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 02/11/20 \_\_\_\_\_