

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	K15E0	1 ,			Springhill Suites			
NPDES Id. No.	NMR10				1101 Central			
	.2/2020	Property Ov	vner		Contractor			
Operator		Cedar Investments, LLC CO Argus Dev.			Jaynes Corp			
Contact name & title		Josh Rogers			Jeff Harper jeff.harper@jaynescorp.com			
e-mail Contact Phone #		jrogers@titan-development.com_ 505-998-0163			250-9351			
COA Inspector		Doug Hughes			Start/End Time:	2:14PM		
Construction Phase:					BILIZED			
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weath	<u>er at time of i</u>	nspection? Clear		ar	Temperature: ~ 76			
Estimated date of last storm 0.25" or greater 10/26/2020								
Item	Deficiency/Corrective Action							
Number	Deficiency/ Corrective Action							
1								
2								
3								
4								
4								
			ГЛОІ	117				
			ΓΑΒΙ		ГІЈ			
2.1	Discharge off site?	(Y/N)	Yes	I				
	,							
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	4/17/20	020	
Notes:								

City of Albuquerque Stormwater Inspector Signature and date:

Doug Hughes (505) 924-3420

jhughes@cabq.gov

Contact information:

12/29/2020

James D. Hughes