



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	K15E034B	Project Name:	Springhill Suites		
NPDES Id. No.	NMR1000VI/NMR1001RP	Location:	1101 Central		
11/12/2020	Property Owner		Contractor		
Operator	Cedar Investments, LLC CO Argus Dev.		Jaynes Corp		
Contact name & title	Josh Rogers		Jeff Harper		
e-mail	jrogers@titan-development.com		jeff.harper@jaynescorp.com		
Contact Phone #	505-998-0163		250-9351		
COA Inspector	Doug Hughes		Start/End Time:	2:14PM	
Construction Phase:	STABILIZED				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	Clear		Temperature: ~	76	
Estimated date of last storm 0.25" or greater	10/26/2020				
Item Number	Deficiency/ Corrective Action				
1					
2					
3					
4					
	STABILIZED				
2.1	Discharge off site? (Y/N)	Yes			
4	Self Inspection Reports	Requested	Latest report Date:	4/17/2020	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Doug Hughes (505) 924-3420
jhughes@cabq.gov

11/12/2020
James D. Hughes