

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Ducie et No.								
Project Name: Location:		Springhill Suites						
		1101 Central		ESC File No.				
Site Contact Name &		Jeff Harper				K15E034B		
Agency		jeff.harper@jaynescorp.com ^{NPI} 06/26/19 Start/End Time: 1210/		NPDES Id. NO.		NMR1001RP		
Inspection Date: CoA Stormwater Inspecto				10/1245hrs				
		r: Timothy E. Sims vertical with site work						
Construction Phase: Type of Inspection: x								
Type of It	ispection: <u>x</u>	Regular	Storm Event	Post Storm	Event >0.25	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	Clea	ar	Temne	rature: ~	85*	
Estimated	date of last s	torm 0.25" o	r greater	21	Tempe	5/11/2019	85	
Item	Deficiency/ Corrective Action							
Number	Bendency corrective Action							
1	Please provide latest SWPPP self-inspection report.							
<u> </u>								
2.1	Discharge off site?	(Y/N)	No	1				
4	-	tion Reports	requested	Latest rer	port Date:	4/30/20	119	
4	Sen inspect	tion hepoilts	requested			4/ 50/ 20	515	

Notes: Jeff thanks for maintaining the eastern most entrance. Site looks great.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155