



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Springhill Suites				
Location:	1101 Central				
Site Contact Name & Agency	Jeff Harper jeff.harper@jaynescorp.com	ESC File No.	K15E034B		
		NPDES Id. No.	NMR1001RP		
Inspection Date:	08/15/19	Start/End Time:	1040/1100hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical with site work				
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☒ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	66*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 8/13/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/15/19