

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Springhill Suites									
Location:	1101 Central									
Site Contact Name & Agency	Jeff Harper				ESC File No.		K15E034B			
	Jaynes Corp				NPDES Id. No.		NMR1001RP			
Inspection Date:	05/13/19		Start/End Time:		1:55		2:20			
CoA Stormwater Inspector:			Curtis Cherne							
Construction Phase:		vertical construction								
Type of Inspection:		Regular		Storm Event		Post Storm Event >0.25"		311/Complaint	X	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	70
Estimated date of last storm 0.25" or greater	5/10/2019		

Item Number	Deficiency/ Corrective Action			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	4/30/2019

Notes:	
No deficiencies observed	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Curtis Cherne PE, 505-924-3420
ccherne@cabq.gov 05/13/2024

05/13/19

Costa a Chem