City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Springhill Suites		
Location:	1101 Central		
Site Contact Name & Agency	Jeff Harper	ESC File No.	K15E034B
	Jaynes Corp	NPDES Id. No.	NMR 1001RP
Inspection Date:	5-3-19	Start/End Time:	9:50 10:40
CoA Stormwater Inspector:	Curtis Cherne		
Construction Phase:	Slab poured, structure walls		

Type of Inspection: [X] Regular [ ] Storm Event [ ] Post Storm Event >0.25" [ ] 311/Complaint [ ] Follow Up

Weather at time of inspection? Clear	Temperature: ~60
Estimated date of last storm 0.25" or greater 4-22-19	

Item Number	Deficiency/ Corrective Action
1.	Domestic waste not in acceptable container - water bottles
2.	A lot of wash-out outside washout facility
3	Concrete wash-out on ground east part of site
4	wash-out on ground - south edge of site
5	wash-out on ground west of fdn
2.1	Discharge off site? (Y/N)
4	Self Inspection Reports — Latest report Date: 4-30-19

Notes:

Removing wash-out around facility while I was there
Jeff to send 2 pics - washout facility and washout near curb

City of Albuquerque Stormwater Inspector Signature and date: Curtis Cherne 5-3-19

Contact information: Curtis Cherne, 505-924-3420
ccherne@cabq.gov