**Jaynes: Springhill Suites** 



# **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

**Inspection Type:** Routine **Date:** 11-26-2019 **Time:** 4:52 PM

Permit Tracking #: NMr1001RPInspector Name: Carlos FloresQualifications: CISECCurrent Weather Conditions: clearDate and Amount of Last Recordable Storm Event: 11-21-2019 .75"

### **Construction Time Line:**

Action	Start Date	Date Complete
Initial BMP Installation	02-01-2019	02-05-2019
Clearing and Grubbing	01-31-2019	02-26-2019
Utility Installation	03-26-2019	
Construction of Structure	02-26-2019	
Final Stabilization		

### Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	$\boxtimes$			
Are areas that have been disturbed, but not under construction been properly stabilized?				Site is active
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence	$\boxtimes$			
Wattles/Filter Sock		$\boxtimes$		
Inlet Protection		$\boxtimes$		
Cut Back Curbs			$\boxtimes$	
Waste Management	$\boxtimes$			
Vehicle Tracking Control	$\boxtimes$			VTC Installed at new entrance
Material Storage			X	
Dust Control	$\boxtimes$			
Street Sweeping	$\boxtimes$			Sweeping scheduled on the weekend for no traffic.
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				Roll-off washout on-site. CWO pit on eastside is not being used.
Discharge Points	$\boxtimes$			
Sanitary Stations	$\boxtimes$			
Stockpiles	$\boxtimes$			Stockpiles are being actively used at this time
Other	$\boxtimes$			

## **Jaynes: Springhill Suites**

### **SWPPP Information:**

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	$\boxtimes$			
Was the SWPPP updated at the time of the inspection?	$\boxtimes$			
Are all certification pages signed?	$\boxtimes$			
Are inspector qualifications in the SWPPP?	$\boxtimes$			
Is there a copy of the NOI and Acknowledgement letter?	$\boxtimes$			
Is there a delegation letter in the SWPPP?	$\boxtimes$			
Was the last inspection/CAL certified?			$\boxtimes$	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Matt Lammers						
	Name	Signature	Date				
Operator	perator: Jeff harper						
	Name	Signature	Date				

### **Additional Comments:**



**Action Log:** 

Action 20g1									
Location	Action Type	Action Required	Date Noted	Date Completed	Initials				
Filter sock - at gate on mulberry and copper	Maintenance	Install filter sock to keep sediment from leaving site. Due to cut in asphalt for utility tie in.	11-22-2019						
inlet protection - eastside of mulberry	Maintenance	install inlet protection	11-19-2019						
Concrete washout pit - Eastside	Maintenance	Concrete washout pit is full. Needs to be emptied	11-05-2019						

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

 Inspector:
 Carlos Flores
 11-26-2019

 Name
 Signature
 Date









