Storm Water Compliance Inspection Form



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine	Date: 02-04-2020	Time: 8:07 AM
Permit Tracking #: NMr1001RP	Inspector Name: Carlos Flores	Qualifications: CISEC
Current Weather Conditions:	Date and Amount of Last Recordable Storm E	vent: 11-21-2019 .75"

Light Snow (Chance)

Construction Time Line:ActionStart DateDate CompleteInitial BMP Installation02-01-201902-05-2019Clearing and Grubbing01-31-201902-26-2019Utility Installation03-26-201902-26-2019Construction of Structure02-26-2019End StabilizationFinal Stabilization02-26-201902-26-2019

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	Site is active
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.	\boxtimes			
Silt Fence	\boxtimes			
Wattles/Filter Sock	\boxtimes			
Inlet Protection		\boxtimes		
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			VTC Installed at new entrance
Material Storage			\boxtimes	
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		Sweeping scheduled on the weekend for no traffic.
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	\boxtimes			Roll-off washout on-site.
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			Stockpiles are being actively used at this time
Other			\boxtimes	

Jaynes: Springhill Suites

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?			\boxtimes	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner: Matt Lammers

Name

Operator: Jeff harper Name

Signature

Signature

Additional Comments:

NMr1001RP

Date

Date



Location	Action Type	Action Required	Date Noted	Date Completed	Initials
inlet protection - eastside of mulberry and copper SE Corner	Maintenance	install inlet protection	11-19-2019		
Inlet protection - East side of mulberry (inlet is not tied in)	Maintenance	Re protect the flat inlet on mulberry	12-17-2019		
Sweep mulberry	Maintenance	Sweep mulberry and replace damaged rock bags	12-31-2019		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Carlos Flores

Name

Signature

02-04-2020 Date **Inspection Photos**







