



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Storm Water Compliance Inspection Form

Inspection Type: Routine	Date: 03-27-2020	Time: 11:10 AM				
Permit Tracking #: NMr1001RP	Inspector Name: Mario Alderete	Qualifications: Inspector				
Current Weather Conditions:	Date and Amount of Last Recordable Storm Event: 11-21-2019 .75"					

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	02-01-2019	02-05-2019
Clearing and Grubbing	01-31-2019	02-26-2019
Utility Installation	03-26-2019	
Construction of Structure	02-26-2019	
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	Site is active
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.	\boxtimes			
Silt Fence	X			
Wattles/Filter Sock	X			
Inlet Protection		\boxtimes		
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control		\boxtimes		Asphalt entrance sweep as needed
Material Storage			\boxtimes	
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		Sweep street as needed
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	\boxtimes			Roll-off washout on-site.
Discharge Points	X			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			
Other			X	

Jaynes: Springhill Suites

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?			\boxtimes	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner: Matt Lammers

Name

Operator: Jeff harper Name

Signature

Signature

Additional Comments:

NMr1001RP

Date

Date



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Inlet protection	Corrective Action	Need to clean and protect inlet	03-27-2020		
Sweep street	Maintenance	Need to sweep up entrance	03-27-2020		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Mario Alderete

apa ShiAP

03-27-2020

Name

Signature

Date

Site Walk Deficiency Photos - Inlet protection



Site Walk Deficiency Photos - Sweep street



Inspection Photos







