

Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 08-11-2020 Time: 9:42 AM

Permit Tracking #: NMr1001RPInspector Name: Tim SlatunasQualifications: CISECCurrent Weather Conditions: ClearDate and Amount of Last Recordable Storm Event: 11-21-2019 .75"

Construction Time Line:

| Action | Start Date | Date Complete |
|---------------------------|------------|---------------|
| Initial BMP Installation | 02-01-2019 | 02-05-2019 |
| Clearing and Grubbing | 01-31-2019 | 02-26-2019 |
| Utility Installation | 03-26-2019 | |
| Construction of Structure | 02-26-2019 | |
| Final Stabilization | 07-06-2020 | |

Site Walk:

| Question | Yes | No | N/A | Comment |
|--|-------------|-------------|-------------|--|
| Is there a proper posting sign? | \boxtimes | | | Sign has been moved, Needs to be put back up. |
| Are areas that have been disturbed, but not under construction been properly stabilized? | | | X | Site is active |
| Velocity Reduction Devices i.e. Check Dams, Berms, Etc. | \boxtimes | | | |
| Silt Fence | | \boxtimes | | |
| Wattles/Filter Sock | | \boxtimes | | |
| Inlet Protection | | \boxtimes | | |
| Cut Back Curbs | | | \boxtimes | |
| Waste Management | \boxtimes | | | |
| Vehicle Tracking Control | | \boxtimes | | |
| Material Storage | | \boxtimes | | Need to make sure all materials are properly stored |
| Dust Control | | | \boxtimes | |
| Street Sweeping | | \boxtimes | | |
| Construction Washouts i.e. Concrete, Paint, Stucco Etc. | | \boxtimes | | Roll-off washout on-site. |
| Discharge Points | \boxtimes | | | |
| Sanitary Stations | \boxtimes | | | |
| Stockpiles | \boxtimes | | | |
| Other | \boxtimes | | | Areas east of the building for bridge will be the new construction area. |

SWPPP Information:

| Question | Yes | No | N/A | Comment |
|--|-------------|----|-------------|---------|
| Is the SWPPP kept on site? | \boxtimes | | | |
| Was the SWPPP updated at the time of the inspection? | \boxtimes | | | |
| Are all certification pages signed? | \boxtimes | | | |
| Are inspector qualifications in the SWPPP? | \boxtimes | | | |
| Is there a copy of the NOI and Acknowledgement letter? | X | | | |
| Is there a delegation letter in the SWPPP? | \boxtimes | | | |
| Was the last inspection/CAL certified? | | | \boxtimes | |

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

| Owner: | Matt Lammers | | | | | | |
|---------|-----------------------|-----------|------|--|--|--|--|
| | Name | Signature | Date | | | | |
| Operato | Operator: Jeff harper | | | | | | |
| | Name | Signature | Date | | | | |

Additional Comments:

They are setting concrete today for the pillars on the south by the ER. There are some maintenance issues as noted on the report.



Action Log:

| Location | Action Type | Action Required | Date Noted | Date Completed | Initials |
|--|-------------|--|------------|-------------------|----------|
| West Staging Area | Maintenance | Need to repair/replace the damaged silt fence | 08-11-2020 | | |
| East area | Maintenance | Need to stand up the silt fence where it is down/stake broke | 08-11-2020 | | |
| Filter sock | Maintenance | Install filter sock on the South side by ER. | 08-04-2020 | | |
| Inlet Protection - Mulberry and copper | Maintenance | Repair or replace inlet protection. | 07-28-2020 | | |
| Cedar Access | Maintenance | Need to add rock to trackout unless they are unable due to sidewalk access | 08-11-2020 | | |
| West Staging Area | Maintenance | Need to make sure all materials are properly stored | 08-11-2020 | | |
| Cedar | Maintenance | Need to sweep the street | 08-11-2020 | | |
| Washout Bin | Maintenance | Need to empty the bin it is full | 08-11-2020 | | |
| Washout Bin | Maintenance | Need to clean up the washout on the ground around the bin | 08-11-2020 | | |

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Tim Slatunas 08-11-2020

Name Signature Date

Site Walk Deficiency Photos - West Staging Area

Site Walk Deficiency Photos - East area



Site Walk Deficiency Photos - Inlet Protection - Mulberry and copper



Site Walk Deficiency Photos - Cedar Access



Site Walk Deficiency Photos - West Staging Area

Site Walk Deficiency Photos - Cedar



Site Walk Deficiency Photos - Washout Bin




Site Walk Deficiency Photos - Washout Bin















8-11-20