**Jaynes: Springhill Suites** 



# **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

**Inspection Type:** Routine **Date:** 07-02-2019 **Time:** 1:06 PM

Permit Tracking #: NMr1001RPInspector Name: Carlos FloresQualifications: CISECCurrent Weather Conditions: ClearDate and Amount of Last Recordable Storm Event: 03-08-2019 0.375

### **Construction Time Line:**

Action	Start Date	Date Complete
Initial BMP Installation	02-01-2019	02-05-2019
Clearing and Grubbing	01-31-2019	02-26-2019
Utility Installation	03-26-2019	
Construction of Structure	02-26-2019	
Final Stabilization		

### Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	$\boxtimes$			
Are areas that have been disturbed, but not under construction been properly stabilized?				Site is active
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.	$\boxtimes$			
Silt Fence		$\boxtimes$		
Wattles/Filter Sock		$\boxtimes$		
Inlet Protection	$\boxtimes$			
Cut Back Curbs			$\boxtimes$	
Waste Management	$\boxtimes$			
Vehicle Tracking Control	$\boxtimes$			Asphalt driveway, sweeping done regularly
Material Storage			$\boxtimes$	
Dust Control	$\boxtimes$			
Street Sweeping		$\boxtimes$		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	$\boxtimes$			Temp washout pit installed
Discharge Points	$\boxtimes$			
Sanitary Stations	X			
Stockpiles	$\boxtimes$			Stockpiles are being actively used at this time
Other		$\boxtimes$		

### **Jaynes: Springhill Suites**

### **SWPPP Information:**

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	$\boxtimes$			
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?	$\boxtimes$			
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?	$\boxtimes$			
Was the last inspection/CAL certified?	$\boxtimes$			

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Matt Lammers						
	Name	Signature	Date				
Operator	Operator: Jeff harper						
	Name	Signature	Date				

### **Additional Comments:**

## **Jaynes: Springhill Suites**



Action Log:

Addition Logi					
Location	Action Type	Action Required	Date Noted	Date Completed	Initials
NW Corner Silt Fence	Maintenance	Re-attach silt fence to temp. fence	06-25-2019		
NW Corner - Filter Sock	Maintenance	Move filter sock back along fence	06-04-2019		
Sweep Street	Maintenance	Sweep mulberry for sediment and place rock bags back along curb	06-18-2019		
Rock Bags	Maintenance	Clean and replace damaged rock bags.	07-02-2019		

<sup>&</sup>quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector:	Carlos Flores	07-02-2019	
-	Name	Signature	Date