Jaynes: Springhill Suites



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 08-13-2019 Time: 1:56 PM

Permit Tracking #: NMr1001RP Inspector Name: Carlos Flores Qualifications: CISEC

Current Weather Conditions: clear Date and Amount of Last Recordable Storm Event: 07-26-2019 1

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	02-01-2019	02-05-2019
Clearing and Grubbing	01-31-2019	02-26-2019
Utility Installation	03-26-2019	
Construction of Structure	02-26-2019	
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			X	Site is active
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.	\boxtimes			
Silt Fence		\boxtimes		
Wattles/Filter Sock	\boxtimes			
Inlet Protection	\boxtimes			
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			Asphalt driveway, sweeping done regularly
Material Storage			\boxtimes	
Dust Control	\boxtimes			
Street Sweeping	\boxtimes			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	\boxtimes			Temp washout pit installed
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			Stockpiles are being actively used at this time
Other	\boxtimes			Site looks good!

Jaynes: Springhill Suites

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	\boxtimes			
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?	\boxtimes			
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?	\boxtimes			
Was the last inspection/CAL certified?	\boxtimes			

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Matt Lammers		
	Name	Signature	Date
Operator	r: Jeff harper		
	Name	Signature	Date

Additional Comments:



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
silt fence - NW corner of building	Maintenance	Repair silt fence	07-26-2019		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector:	Carlos Flores	08-13-2019	
_	Name	Signature	Date