Storm Water Compliance Inspection Form



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Storm Event	Date: 09-17-2019	Time: 1:33 PM	
Permit Tracking #: NMr1001RP	Inspector Name: Carlos Flores	Qualifications: CISEC	
Current Weather Conditions:	Date and Amount of Last Recordable Storm Ev	ent: 09-17-2019 .25	

Thunderstorms (Isolated)

Construction Time Line:		
Action	Start Date	Date Complete
Initial BMP Installation	02-01-2019	02-05-2019
Clearing and Grubbing	01-31-2019	02-26-2019
Utility Installation	03-26-2019	
Construction of Structure	02-26-2019	
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	Site is active
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence	\boxtimes			
Wattles/Filter Sock	\boxtimes			
Inlet Protection		\boxtimes		Remove sediment from inlet protection on mulberry and repair.
Cut Back Curbs			\boxtimes	
Waste Management	X			
Vehicle Tracking Control		\boxtimes		
Material Storage			\boxtimes	
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	\boxtimes			Roll-off washout on-site.
Discharge Points	X			
Sanitary Stations	Χ			
Stockpiles	\boxtimes			Stockpiles are being actively used at this time
Other	\boxtimes			

Jaynes: Springhill Suites

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?			\boxtimes	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner: Matt Lammers

Name

Operator: Jeff harper Name

Signature

Signature

Additional Comments:

NMr1001RP

Date

Date



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Replace rock bag on east side of Mulberry at southern most drive pad.	Maintenance	Replace rock bag on east side of Mulberry at southern most drive pad.	09-03-2019		
Remove sediment from inlet protection on mulberry and repair.	Maintenance	Remove sediment from inlet protection on mulberry and repair.	09-03-2019		
Close access to cedar or install VTC	Corrective Action	Close access to Cedar or install VTC to prevent sediment tracking on cedar	09-17-2019		
Sweep Street - Cedar	Maintenance	Sweep street for sediment	09-17-2019		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Carlos Flores Name

Signature

09-17-2019 Date

Inspection Photos







