



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Springhill Suites				
Location:	1101 Central				
Site Contact Name & Agency	Jeff Harper jeff.harper@jaynescorp.com	ESC File No.	K15E034B		
		NPDES Id. No.	NMR1001RP		
Inspection Date:	05/07/19	Start/End Time:	1415/1430hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical with site work				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input checked="" type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	75*
Estimated date of last storm 0.25" or greater	4/22/2019		

Item Number	Deficiency/ Corrective Action			
1	Washout south of concrete washout facility			
2	Washout south west corner of building			
3	Domestic waste not in acceptable container- water bottles			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	4/30/2019

Notes:	Jeff did notice the northeastern most access point off of Cedar will require a trackout pad.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 05/07/19