

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Na	me:	Nob Hill Apartments Urban Living						
Location:		4101 Central Ave NE						
Site Contact Name &		Mike Davis - Alliance		ESC File No.	K17E073			
Agency		medavis@resco.com		NPDES Id. No.	NMR1001V0			
Inspection Date:			Start/End Time:	1220/1230hrs				
	water Inspecto							
Construction Phase:					dations			
Type of Ir	nspection: X	Regular	Storm Event	Post Storm B	Event >0.25"	311/Complaint	Follow Up	
						· •	*	
Weather at time of i Estimated date of last s		nspection?	Ptly C	loudy	Tempe	rature: ~ 11/27/2019	55*	
		10/11/0.25	orgreater			11/2//2019		
Item			Deficier	ncy/Correctiv	e Action			
Number	Deficiency/ Corrective Action							
	no issues observed with this inspection							
2.1	Discharge off site?	(Y/N)	No					
4	-	tion Reports		Latest rer	oort Date:	1/24/20	020	
		-1				-, = ·, - ,	-	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155