



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Nob Hill Apartments Urban Living				
Location:	4101 Central Ave NE				
Site Contact Name & Agency	Mike Davis - Alliance	ESC File No.	K17E073		
	medavis@resco.com	NPDES Id. No.	NMR1001V0		
Inspection Date:	03/24/20	Start/End Time:	1000/1015hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Ptly Cloudy	Temperature: ~	51*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action			
	no issues observed with this inspection			
	***Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	1/24/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 03/24/20