City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Nob Hill Apartments Urban Living		
Location:	4101 Central Ave NE		
Site Contact Name & Agency	Mike Davis - Alliance	ESC File No.	K17E073
	medavis@resco.com	NPDES Id. No.	NMR1001V0
Inspection Date:	06/17/20	Start/End Time:	0955/1015hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical		

Type of Inspection:	X	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up

Weather at time of inspection?	Clear	Temperature: ~	82*
Estimated date of last storm 0.25" or greater		6/1/2020	

Item Number	Deficiency/ Corrective Action			
1	Mitigate mortar (cementous) washouts [mortar hopper/facility]			
2	Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	4/3/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2020.06.18 09:10:11 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 06/17/20