

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Nar	me:	Nob Hill Apartments Urban Living							
Location:		4101 Central Ave NE							
Site Contact Name &		Mike Davis - Alliance		ESC File No.	K17E073				
Agency		medavis@resco.com		NPDES Id. No.		NMR1001V0			
Inspection Date:			tart/End Time: 09	930/0955hrs					
	water Inspecto								
Construction Phase:		vertical							
Type of Ir	nspection: x	Regular	Storm Event	Post Storm E	event >0.25"	311/Complaint >	Follow Up		
Weath	er at time of i	nenoction?	Clea	or I	Tompo	rature: ~	77*		
Estimated	date of last s	torm 0.25" c	or greater	ai	Tempe	7/25/2020	//		
Item			Deficiend	cy/ Correctiv	e Action				
Number									
1	Please provide latest SWPPP self-inspection report.								
2	Domestic waste not in acceptable refuse location								
3	Construction waste not in acceptable refuse location								
4	Red remnants of washout on north side of site. Please mitigate								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	6/12/20)20		
		•				· ·			

Notes:		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155