



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Nob Hill Apartments Urban Living		
Location:	4101 Central Ave NE		
Site Contact Name & Agency	Mike Davis - Alliance medavis@resco.com	ESC File No.	K17E073
		NPDES Id. No.	NMR1001V0
Inspection Date:	09/09/20	Start/End Time:	0950/01020hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	46*
Estimated date of last storm 0.25" or greater	8/1/2020		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 8/28/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 09/09/20