



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	De Anza		
Location:	4301 Central		
Site Contact Name & Agency	Dan - HB Construction danf@hbconstruction.com	ESC File No.	K17E106
		NPDES Id. No.	NMR10013H
Inspection Date:	05/28/19	Start/End Time:	
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☐ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	60*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	no issues noted		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 5/10/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 05/28/19