



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	De Anza		
Location:	4301 Central		
Site Contact Name & Agency	Larry - HB Construction	ESC File No.	K17E106
	larryh@hbconstruction.com	NPDES Id. No.	NMR10013H
Inspection Date:	11/20/19	Start/End Time:	1055/1105hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	interior		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	58*
Estimated date of last storm 0.25" or greater	10/4/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
	**Please provide latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 9/9/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 11/20/19