

**INSPECTION REPORT****GENERAL INFORMATION**

**DATE OF INSPECTION:** 4/8/2019

**COMPANY NAME:** HB Construction

**PROJECT NAME:** De Anza Motor Lodge

**LOCATION:** 4301 Central Ave NE, Albuquerque, New Mexico, 87106

**TRACKING NO:** NMR10013H

**COMPLIANCE EVALUATION:** Marginal

**TYPE OF INSPECTION:** 7Day

**START TIME:** 8:15 AM

**END TIME:** 8:45 AM

**INSPECTOR'S NAME:** Kasey Anderson

**INSPECTOR'S TITLE:** Environmental Inspector

**INSPECTOR'S QUALIFICATIONS:** Storm Water Qualified Person

**INSPECTOR'S CONTACT:** 505-280-7766

**PHASE OF CONSTRUCTION:** ☐ Clear and Grub ☐ Excavation ☒ Building (vertical)  
☒ Rough Grading ☒ Infrastructure ☒ Final Grading  
☐ Final Stabilization

**WEATHER INFORMATION**

**HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?** ☐ Yes ☒ No

**WEATHER AT TIME OF THIS INSPECTION:** Clear

**TEMPERATURE:** 56

**HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?** ☐ Yes ☒ No

**ARE ANY DISCHARGES OCCURRING NOW?** ☐ Yes ☒ No

**ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?** ☐ Yes ☒ No

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	PHOTO
1	Wattles/Socks/Log Roll	None	Re-install	West side of project is in needs new silt fence or wattles.	125	LF	
2	Wattles/Socks/Log Roll	None	Upgrade	NW corner wattle needs to extend 5 more feet to the south.	5	LF	
3	Sediment	Clean	None	Sweep north sidewalk (inside and outside fence), sweep west sidewalk, and sweep Graceland's gutters.	3	EA	

## GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	Added a new rain gauge to the SWPPP board.
2	Are steep slope areas not actively being worked properly stabilized?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
3	Are disturbed areas not actively being worked properly stabilized?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
5	Are discharge points and receiving waters free of any sediment deposits?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input checked="" type="radio"/> Yes <input type="radio"/> No	Address the western BMPs, and sweep Graceland's and Copper's gutters/sidewalks.
6	Is trash/litter from work areas collected and placed in covered dumpsters?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
10	Are offsite flows entering the construction site?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
13	Are non-stormwater discharges properly controlled?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
15	Are changes to the SWPPP necessary at this time?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	
16	Are dust control measures being properly implemented?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A	<input checked="" type="radio"/> Yes <input type="radio"/> No	Dust can still move under the privacy fence where BMP protection is missing.
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A	<input type="radio"/> Yes <input checked="" type="radio"/> No	

## CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

**INSPECTED BY:**

Kasey Anderson

**DATE:**

April 08, 2019

**SIGNATURE AND AFFILIATION:**



**CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

**PRINT NAME AND TITLE:** \_\_\_\_\_, **DATE:** \_\_\_\_\_

**SIGNATURE:** \_\_\_\_\_