

City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	formation				
ESC File No.	K19E1	108A Project Name:			Fiesta Subaru			
NPDES Id. No.	NMR10	004J9	Location:		7100 Lomas Blvd NE			
7/21/2023		Owner	•	•	Contractor			
Operator		7100 Lomas, LLC			Hart Construction, Inc.			
Contact name & title		Derek Kulach			Andy Hart			
e-mail		derek kulach@fiestaautogroup.com			ahart@hartconstruction.com			
Contact Phone #		505-715-2442			505-345-4001			
COA Inspector		Chancellor English			Start/End Time:	/End Time: 9am		
Construc	ction Phase:			CO, st	abilized	•		
Type of In	spection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i		Clea	r	Temper	rature: ~	90	
	date of last s				i i emper	5/22/2023		
		101111 0125	or greater					
ltem Number	Deficiency/ Corrective Action							
1	The owner's NOI has expired and the contractor has filed NOT. Construction waste dumpster is still							
	onsite. Stabilization has been initiated, and posting and BMPs have been removed. Required mitigation: File for NOT. In accordance with City Ordinance § 14-5-2-11(C)(1), self-inspections must							
	continue until the site is "determined as stabilized by the city." The property owner/operator is							
	responsible for determining when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are							
	satisfied and then for filing their Notice of Termination (NOT) with the EPA. Each operator may							
		-		-	-			
	terminate CGP coverage only if one or more of the conditi- After filing the NOT with the EPA, the property owner is re							
	-		e EPA, the property	owner is res	ponsible for re	equesting a Deter	mination of	
	Ctabilization fr	om the City						
2.1	Discharge off site?	(Y/N)	no					
	Self Inspect							

Notes:							
No prior inspections performed.							

City of Albuquerque Stormwater Inspector Signature and date: 7/24/2023

Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov

<u>Chancellor English</u>