



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	K19E108	Project Name:	Cooperage Demolition		
NPDES Id. No.		Location:	7220 Lomas Blvd. NE		
5/28/2021	Owner	Contractor			
Operator	C&C Demolition Services				
Contact name & title	David Tarin				
e-mail	cancservices@live.com				
Contact Phone #	505-280-1730				
COA Inspector	Thomas Evans		Start/End Time:	11:00 AM-11:15 AM	
Construction Phase:	Demolition				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint Follow Up	
Weather at time of inspection?	clear		Temperature: ~	80	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	None.				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	Yes			
4	Self Inspection Reports	Requested	Latest report Date:		

Notes:	The South half of the building has been demolished. Some water has exited the site beneath the wattle, but no sediment has entered the street.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 06/03/2021