

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name and Location		Fiesta Kia 7400 Lomas Blvd NE							
Site Contact Name & Agency		Rick Gonzales Brian			ESC File No. NPDES ID No.	K19E152 NMR1001E8- Hart			
Date of Inspection		11/08/18			Start/End Time	1:45pm - 2:30pm			
COA Inspector Name		Curtis Cherne, Stormwater Quality							
Describe Present Phase of Construction		Vertical Construction							
Type of Inspection:									
☐ Regular ☐ During storm event ☐ Post-storm event (> 0.25 inch) ☐ 311 / Complaint Response ☐ Follow-Up									
Weather Information									
Weather at time of this inspection?       Temperature: ~ 65 F°         ☑Clear ☐Cloudy ☐Rain ☐Sleet ☐Fog ☐Snowing ☐Windy									
Has there been a storm event since the site was Permitted? XYes □No  Amount: □< ½" □½" to ¾" □Snow "									
			Inspecti	on					
			G .:	I					
CGP	BMP / Activity	Maintenance Required? (1)	Corrective Action Required? (2)	Location and	l Notes				
1.5	Post a Notice								
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.4	Minimize sediment track-out								
2.2.5	Manage stockpiles								

2.2.6	Minimize Dust			
2.2.10	Protect Storm Drain Inlets			
2.2.10	Protect Storm Drain Inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site.			
2.2.14	Stabilize exposed portions of the site.			
2.2.14	Stabilize exposed portions of the site.			
2.2.14	Stabilize exposed portions of the site.			
2.3.1	Equipment and Vehicle Fueling			
2.3.2	Equipment and Vehicle Washing			
2.3.3	Building Material Storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and Domestic Wastes		X	Place acceptable waste containers around site
2.3.3	Construction and Domestic Wastes			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		Х	Washout Receptacle is leaking and must be replaced or lined to prevent leaks.
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site?		□Yes <b>X</b> No	
4	Self-Inspection Reports	1.	1 1 0 11 1	Latest Report Date: 10/26/18

Notes: (City Inspector Use) Items in compliance can be left blank.

(1) Maintenance is to be complete by the end of the next business day.

(2) Corrective Actions are to be complete within 7 days.

Notes: The concrete washout receptacle on site is leaking please replace within the next seven days. There is litter all over the site. Place waste containers around the site within the next seven days.

Signature

City of Albuquerque Stormwater Inspector Signature and Date:

11/08/18

Date

Contact Info: Curtis Cherne, P.E. 505-924-3420, ccherne@cabq.gov