

## City of Albuquerque Stormwater Construction Site Inspection Report

			General In	formation			
Project Nai	ne:	Holiday Inn Ex	press				
Location:		Copper Pointe					
Site Contact Name & Agency		Owen Johnson, Premier Hospitality ESC File No. K21E009H3					
		NPDES Id. No. NMR1001FF					
Inspection Date:		01/13/20 Start/End Time: 1200/1210hrs					
	water Inspecto		mothy E. Sims				
Construction Phase: STABILIZED							
Type of Inspection: x		Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Z Z	riegulai				(222) COMPIGNITY	Tronott op
Weath	er at time of i	nspection?	Clea	r I	Tempe	rature: ~	41*
Weather at time of inspection? Clear Temperature: ~ 41* Estimated date of last storm 0.25" or greater							
	Gate or last s		Al carel				
Item	Deficiency/ Corrective Action						
Number	Deficiency/ corrective /tetion						
	CTADII 17ED						
	STABILIZED						
2.1	Discharge off site?	(Y/N)	No				
4	-	tion Reports		Latest rep	ort Date:		
-	- 1	1					
Notes:							

 $\label{lem:city} \textbf{City of Albuquerque Stormwater Inspector Signature and date:}$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

01/13/20