



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Maverik		
Location:	650 Juan Tabo		
Site Contact Name & Agency	Jason - Insight Const jason@insisghtnm.com	ESC File No.	K22E059
		NPDES Id. No.	NMR10022L
Inspection Date:	01/27/20	Start/End Time:	1115/1130hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical		
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☐ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	43*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 1/15/2020

Notes:	This project requires SWPPP self-inspection reporting until the work order is complete on Juan Tabo.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/27/20